

What does it mean that BCM has lost communication with the base station

Source: <https://www.aitesigns.co.za/Sat-20-Apr-2019-4640.html>

Website: <https://www.aitesigns.co.za>

This PDF is generated from: <https://www.aitesigns.co.za/Sat-20-Apr-2019-4640.html>

Title: What does it mean that BCM has lost communication with the base station

Generated on: 2026-03-24 03:42:28

Copyright (C) 2026 AITESIGNS SOLAR. All rights reserved.

For the latest updates and more information, visit our website: <https://www.aitesigns.co.za>

The BCM-B receives its primary power from a fused feed. A blown fuse, intermittent fuse contact, or a failing power-distribution module can starve the BCM of voltage, leading to a loss of ...

In this post, we have explored the various causes of lost communication with the Body Control Module, including wiring and connector issues, faulty sensors and actuators, ...

In summary, the U0140 trouble code signifies a loss of communication between your car's main computer and the BCM, often caused by wiring issues, faulty connectors, or a ...

The U0140 code stands for "Lost Communication With Body Control Module (BCM)", which usually means the BCM isn't properly transmitting or receiving signals from ...

Diagnostic Trouble Code (DTC) U0140 indicates a faulty Body Control Module (BCM) or bad wiring within your vehicle.

In summary, the U0140 trouble code signifies a loss of communication between your car's main computer and the BCM, often ...

The U0141 diagnostic trouble code translates to "Lost Communication with Body Control Module "A"" (BCM). This code is set by other control units, such as the Engine Control ...

The C0291 diagnostic trouble code (DTC) refers to "Lost Communications With BCM," which means that the communication between the Body Control Module (BCM) and other control ...

This error points to a communication issue between the Body Control Module (BCM) and other modules

What does it mean that BCM has lost communication with the base station

Source: <https://www.aitesigns.co.za/Sat-20-Apr-2019-4640.html>

Website: <https://www.aitesigns.co.za>

within the vehicle. Possible causes of this error include poor connections, damaged ...

The OBDII code U014C indicates that there is a loss of communication between the vehicle's control module and the Body Control Module (BCM), meaning the BCM is not responding or is ...

This error points to a communication issue between the Body Control Module (BCM) and other modules within the vehicle. Possible causes of this error ...

The U1064 code indicates that the engine control module (ECM) has lost communication with the body control module (BCM) in the vehicle. The BCM is responsible for controlling various ...

Web: <https://www.aitesigns.co.za>

